

आज मिति २०७५ बैशाख ११ गतेका दिन यस विभागका महानिर्देशक श्री मुक्तिप्रसाद आचार्यज्यूको अध्यक्षतामा IT Products (IFB No. DOLM/G/NCB-6/2074/075) खरिद कार्यको गोरखापत्र दैनिकमा मिति २०७४ चैत्र १५ गते प्रकाशित बोलपत्र आह्वान सम्बन्धी सूचनाको मिति २०७५ बैशाख ७ गते बसेको Pre-bid बैठकमा विभिन्न बोलपत्रदाताहरूदाताहरूबाट पेश गरेका Pre-bid Query का सम्बन्धमा तपशिल बमोजिमका उपस्थितिमा बैठक बसी देहाय बमोजिमको निर्णय गरियो ।

उपस्थिति:

१. महानिर्देशक श्री मुक्ति प्रसाद आचार्य, भूमिसुधार तथा व्यवस्थापन विभाग

२. प्रमुख लेखा नियन्त्रक श्री हिण्यप्रसाद पराजुली, भूमिसुधार तथा व्यवस्थापन विभाग

३. निर्देशक(सू.प्र.) श्री रामदत्त भट्ट, भूमिसुधार तथा व्यवस्थापन विभाग

४. शाखा अधिकृत श्री रत्नमान उदास, भूमिसुधार तथा व्यवस्थापन विभाग, खरिद ईकाइ प्रमुख

५. लेखा अधिकृत हरिकृष्ण हायजु, भूमिसुधार तथा व्यवस्थापन विभाग, खरिद ईकाइ सदस्य

६. कम्प्युटर अधिकृत हिरागोपाल महर्जन, भूमिसुधार तथा व्यवस्थापन विभाग, खरिद ईकाइ सदस्य

७. कानून अधिकृत श्री विष्णुबहादुर घर्ती, भूमिसुधार तथा व्यवस्थापन विभाग

निर्णयहरू:

१. बोलपत्रदाताहरूबाट Pre-bid बैठकमा पेश भएका Pre-Bid Query का सम्बन्धमा देहाय बमोजिम स्पष्ट पारी e-Procurement portal [www.bolpatra.gov.np/ppmo](http://www.bolpatra.gov.np/ppmo) मार्फत् बोलपत्रदाताहरूलाई जानकारी गराउने निर्णय गरियो:-

क. Procurement of Supply and Delivery of IT Equipment- Slice -04- VPN Router/Firewall -35 units, Network Manageable Switch - 35 units and Firewall -2 units, Contract Identification No: DOLM/G/NCB-6.04/2074/075

| Sl.No | Bidding Document Reference                        | Bidder's queries   | Clarification from the Purchaser                          |
|-------|---|--|---|
| 1.    | Section II: Bid Data Sheet, Page no. 31, ITB 19.2 | It is said that Manufacturer's Authorization or / Authorization for Authorized Distributor/ reseller is required.<br><br>For the best side for the Department of land Reform and Management; in order to get the sound support, get other issues like while updating firmware, warranty issues and etc. It would be better if only vendor partner whether distributor/reseller only participate if by they have a particular Manufacturer Authorization Letter for particular project. Due to this, there won't be any issue in future support even the reseller/ distributor close down their office. In such situation, Original Equipment Manufacturer will be liable for the solving all the issue. So, we request you to ask for Manufacturer's Authorization Letter rather than reseller/ distributor certificate. | Change not required.<br>Please refer to Bidding Document. |



| 2. Section V: Schedule of Requirements, 3. Technical Specification of firewall, Page no. 59 | 1. How many Concurrent User is required,   | Change not required. Please refer to Bidding Document. |              |         |                     |                    |                          |                     |                 |                    |            |                          |                  |
|---|--|--|--------------|---------|---------------------|--------------------|--------------------------|---------------------|-----------------|--------------------|------------|--------------------------|------------------|
|   | 2. Is FW having Multi engine sandboxing to prevent zero day attract.   |  |              |         |                     |                    |                          |                     |                 |                    |            |                          |                  |
|   | 3. Real time deep memory inspection to protection against the attacks which happens on memory  |  |              |         |                     |                    |                          |                     |                 |                    |            |                          |                  |
|   | 4. Should have not have any limit of file size for AV Scanning   |  |              |         |                     |                    |                          |                     |                 |                    |            |                          |                  |
|   |  |  |              |         |                     |                    |                          |                     |                 |                    |            |                          |                  |
|   | <table border="1"> <thead> <tr> <th>Particulars</th> <th>Requirements</th> <th>Changes</th> </tr> </thead> <tbody> <tr> <td>Concurrent Sessions</td> <td>Minimum 2 Millions</td> <td>Connections 1.5 millions</td> </tr> <tr> <td>Firewall throughput</td> <td>Minimum 10 Gbps</td> <td>3.0 Gbps or Higher</td> </tr> <tr> <td>Management</td> <td>SSH, Telnet, Http, Https</td> <td>SSH, Http, Https</td> </tr> </tbody> </table> | Particulars  | Requirements | Changes | Concurrent Sessions | Minimum 2 Millions | Connections 1.5 millions | Firewall throughput | Minimum 10 Gbps | 3.0 Gbps or Higher | Management | SSH, Telnet, Http, Https | SSH, Http, Https |
| Particulars   | Requirements   | Changes  |              |         |                     |                    |                          |                     |                 |                    |            |                          |                  |
| Concurrent Sessions   | Minimum 2 Millions   | Connections 1.5 millions                               |              |         |                     |                    |                          |                     |                 |                    |            |                          |                  |
| Firewall throughput   | Minimum 10 Gbps  | 3.0 Gbps or Higher                                     |              |         |                     |                    |                          |                     |                 |                    |            |                          |                  |
| Management  | SSH, Telnet, Http, Https   | SSH, Http, Https                                       |              |         |                     |                    |                          |                     |                 |                    |            |                          |                  |

ख. Procurement of Supply and Delivery of IT Equipment- Slice, 05 Server-2 units, Contract Identification No: DOLM/G/NCB- 6.05/2074/075

| Sl.No | Bidding Document Reference   | Bidder's queries  | Clarification from the Purchaser                       |
|-------|--|---|--|
|       | Section II: Bid Data Sheet, Page no. 32, ITB 19.2  | <p>It is said that Manufacturer's Authorization or / Authorization for Authorized Distributor/ reseller is required.</p> <p>For the best side for the Department of land Reform and Management; in order to get the sound support, get other issues like while updating firmware, warranty issues and etc. It would be better if only vendor partner whether distributor/reseller only participate if by they have a particular Manufacturer Authorization Letter for particular project. Due to this, there won't be any issue in future support even the reseller/ distributor close down their office. In such situation, Original Equipment Manufacturer will be liable for the solving all the issue. So, we request you to ask for Manufacturer's Authorization Letter rather than reseller/ distributor certificate.</p> | Change not required. Please refer to Bidding Document. |
|       | Section V: Schedule of Requirements, 3. Technical Specification, Page 56, Items No. 6: Processor | <p>The processor Intel Xenon Processor has 40 MB Cache. The new version of Intel Kabby Lake architecture does not have 40 MB cache. The Kabby lake architecture is in the new generation Servers and will perform more efficiently than the previous Architecture.</p> <p>Change to: The Cache should be changed to minimum 22 MB Cache as all the new generation will come with those specification.</p> <p>Reason: Intel new generation microprocessor have less amount of cache but performance is twice as better.</p> <p>Thus, I would once again like to request you to do change as in need for the bid.</p>   | Change not required. Please refer to Bidding Document. |




Government of Nepal  
Ministry of Agriculture, Land Management and Cooperatives  
Department of Land Reform and Management  
Babarmahal, Kathmandu, Nepal

*Clarifications on the queries from the prospective bidders*

Clarification No-1

This is to notify that Ministry of Agriculture, Land Management and Cooperatives, Department of Land Reform and Management Babarmahal, Kathmandu, Nepal has made following clarifications on the queries from the prospective Bidders on the Bidding Documents for the Procurement of Supply and Delivery of IT Equipment- Slice, 05 Server-2 units, Contract Identification No: DOLM/G/NCB- 6.05/2074/075 published in the daily Gorkhapatra newspaper on March 29, 2018.

| Sl.No | Bidding Document Reference   | Bidder's queries  | Clarification from the Purchaser                          |
|-------|--|---|---|
| 1     | Section II: Bid Data Sheet, Page no. 32, ITB 19.2  | <p>It is said that Manufacturer's Authorization or / Authorization for Authorized Distributer/ reseller is required.</p> <p>For the best side for the Department of land Reform and Management; in order to get the sound support, get other issues like while updating firmware, warranty issues and etc. It would be better if only vendor partner whether distributor/reseller only participate if by they have a particular Manufacturer Authorization Letter for particular project. Due to this, there won't be any issue in future support even the reseller/ distributor close down their office. In such situation, Original Equipment Manufacturer will be liable for the solving all the issue. So, we request you to ask for Manufacturer's Authorization Letter rather than reseller/ distributor certificate.</p> | Change not required.<br>Please refer to Bidding Document. |
| 2     | Section V: Schedule of Requirements, 3. Technical Specification, Page 56, Items No. 6: Processor | <p>The processor Intel Xenon Processor has 40 MB Cache. The new version of Intel Kabby Lake architecture does not have 40 MB cache. The Kabby lake architecture is in the new generation Servers and will perform more efficiently than the previous Architecture.</p> <p>Change to: The Cache should be changed to minimum 22 MB Cache as all the new generation will come with those specification.</p> <p>Reason: Intel new generation microprocessor have less amount of cache but performance is twice as better.</p> <p>Thus, I would once again like to request you to do change as in need for the bid.</p>   | Change not required.<br>Please refer to Bidding Document. |

  
Ratna Man Udas  
Section Officer  
April 24, 2018